

# **DETAILS OF WORKS ALREADY COMPLETED YEAR WISE DURING LAST FIVE YEARS**

**NAME OF THE CLIENT: INDIAN OIL CORPORATION LTD.**

S. No.	LOA NO.	Work Order Value (In Lacs)	Compl. Certificate	Year of Completion
<b>YEAR 2009-2010</b>				
1.	Excavation, Sand blasting and providing coating with CTE tape in C-M section with PU Coating material supply in SMPL LOA No. 17790465 dt 23-07-08	218	Completed	2009
2.	Excavation, Sand blasting and providing coating with CTE tape in C-M section in SMPL LOA No. 17885112 dt 13.02.09	223	Completed	2010
3.	Excavation, Sand blasting and providing coating with CTE tape in C-M section in SMPL LOA No. 17885757 dt 17-02-09	297	Completed	2010
3.	Excavation, Sand blasting and providing coating with cold tape Coating in M-D section in MJPL LOA No. 17899658 dt 12-03-09	124	Completed	2011
4.	Supply and application of 100% solid poly urethane paint on Mounded LPG bullets of BPCL at Pune, Nasik, Pitampur, Jaipur, Salempur & Larlu Clients Name- Fabtech Project Ltd Pune	160	Completed	2011
1	Maintenance and inspection of M S Storage Tanks of Indian Oil Corporation Ltd at Chaksu. LOA No: 23088367( Consortium of MKRBPPL And JGPIPL)	235	Completed	April 2011
2	Maintenance and inspection of M S Storage Tanks of	325	Completed	April 2011

	Indian Oil Corporation Ltd at Viramgam. LOA No: 23088356 (Consortium of MKRBPPL And JGPIPL)			
3	Fabrication of M S Storage Tank size 12 m x 9 mtrs at Indian Oil Corporation ITd , Chandrapur LOA No: 23176611 Client Name M.K. Roy & Bros Projects Pvt. Ltd.	66	Completed	2010-2011
4	Replace ment of Sprinkler Lines of Tanks at Indian Oil Corporation Ltd,Vadinar LOA No: 23286873 Client Name M.K. Roy & Bros Projects Pvt. Ltd.	47.4	Completed	2010-2011
5	Coat & Wrap In MJPL IOCL, Panipat LOA No. 23294403	31	Completed	2011
6	Maintenance of pipeline at IOCL, Kakinada LOA No.23240339	27	Completed	2011
7	Coat and Wrap, Cleaning the pipe by sand blasting, priming, coating with PU material, sleeving, Holiday testing and backfiling In WRPL Bareja Loa no.23376260	200	Completed	2010-2011
8	Replacement of Foam pourer lines with providing Internal Coating with Glass flake coatings at Indian Oil Corporation Ltd ,Chaksu- Job includes Internal coating of pipelines of dia 8",6",4"and 3" LOA No: 23290628 Client Name M.K. Roy & Bros Projects Pvt. Ltd.	145	Completed	2010-2011
9	Coat and wrap, cleaning the pipe by sand blasting, Primer application on SMPL, KSPL, &KAPL V-M Chaksu loa No.23387835	157	Completed	2010-2011

**YEAR 20011-2012**

1	Provision of Sprinkler System For All Tanks at Kadapa Depot LOA No:23522854	118	Completed	
2	Roof Drain Rectification Of Crude Oil Storage Tanks in WRPL LOA No: 23477676	52		
3	Impervious Tk Dvk. Mundra Terminal	382	Completed	2012
4	IPS anamoly rectification by using cold tape or liquid epoxy Viramgam LOA.No:23539888	23	Completed	2011-12
5	IPS anamoly rectification by using cold tape or liquid epoxy Sidhpur LOA.No: 23539891	77	Completed	
6	Leak Site work near village umrala_mathura LOA.No23552284	32	Completed	2011-12
7	IPS Chaksu LOA.No:23719799	113	Completed	2011-12

**YEAR 20013-2014**

1	C/W-RAJOLA_SENDRA LOA.No:23794780	346	Completed	2014
2	C/W SENDRA_RAM SAR LOA No:23794782	274	Completed	2014
3	WEATHER SHEILD MUNDRA LOA .No: 23822992	31	Completed	2014
4	C/W RAJOLA LOA No:24005286	122	Completed	2014

---

**YEAR 2014-2015**

1	Dig Site Verification Sanganer-Rewari Section NRPL LOA No:24065482	33	Completed	2014-2015
2	Dig Site Verification Rewari-Panipat Section NRPL LOA No:24065528	37	Completed	2014-2015
3	PU COATING OF 2 KMS CHAKSU LOA NO:24070474	45	Completed	2014-2015
4	IPS ANMOLY KOT-SALWAS GROUP-A LOA No:24150157	23	Completed	2014-2015
5	IPS ANMOLY KOT-SALWAS GROUP-B LOA No:24150171	30	Completed	2014-2015
6	IPS ANMOLY KOT-SALWAS GROUP-C LOA No:24150183	40	Completed	2014-2015
7	IPS ANMOLY KOT-SALWAS GROUP-DLOA No:24150189	18	Completed	2014-2015
8	ROSOV MUNDRA PART-1 LOA No:24209974	160	Completed	2014-2015
9	INSTALLATION OF SECONDARY SEAL MUNDRA LOA No:24199105	109	Completed	2015
10	ROSOV MUNDRA PART-2 LOA No:24209985	160	Completed	2015
11	ROSOV VIRAMGAM PART-1 LOA No:24278208	138	Completed	2015
12	ROSOV VIRAMGAM PART-2 LOA No:24278202	110	Completed	2016
13	Inspection of Non-Piggable Group_A LOA NO:24288004	26	Completed	2015

14	Inspection of Non-Piggable Group_B LOA NO:24288014	33	Completed	2015
15	Inspection of Non-Piggable Group_C LOA NO:24288034	46	Completed	2015
16	Combined Station CSW Sanganer LOA NO:24313941	281	Completed	2016
17	Combined Station work in Beawar LOA NO:24313935	274	Completed	2016
18	Setting of Receipt of water supplied at WRPL Gujarat LOA NO:24343278	71	Completed	2016
19	PU COATING VIRAMGAN LOA No:24360473	452	Completed	2016
20	PU COATINGVADINAR-JAMNAGAR LOA No:24360472	350	Completed	2016
21	TAPE COATING ABU-ROAD LOA No: 24492386	301	Completed	2016
22	TAPE COATING VADINAR LOA No: 24492384	309	Completed	2016
23	<b>GSPL</b> COATING REFURBISHMENT AT BHARUCH	281	RUNNING	
24	Maintenance and inspectionOF Crude Oil Storage of Tank No-MT-01 at MUNDRA LOA No:24527382	515	Completed	2016
25	IPS Rewari-Panipat LOA: 24575333	35	Completed	2016
26	Maintenance of Row Facilities Under Sendra Base LOA No : 24596589	18	RUNNING	

27	M&I Viramgam LOA No: 24600190	28	Completed	2016
28	Desluding of SS_10 Tank at Vadinar LOA No: 24608544	16	Completed	2016
29	Cutting of Station Pipe with Cold Cutting Machine at WRPL Gauridad LOA No: 24661840	3	Completed	2016
30	Casing Extension Work at MPPL Panipath LOA No:24682918	17	Completed	2016
31	Coating Refurbishment of 24" Mainline with PU Coating Sendra LOA No: 24692429	186	Completed	2016
32	Coating Refurbishment of 52.606 Km with cold Applied Tape Group-A Siddhpur-Abu Road LOA No:24706493	106	RUNNING	
33	Coating Refurbishment of 52.606 Km with cold Applied Tape Group-B Siddhpur-AbuRoad-Kot LOA No:24706494	216	RUNNING	
34	Coating Refurbishment of 52.606 Km with cold Applied Tape Group-C Kot-Rajola LOA No:24706495	43	Completed	2016
35	Coating Refurbishment of 52.606 Km with cold Applied Tape Group-D Ramsar-Chaksu LOA No:24706496	115	RUNNING	

36	Coating Refurbishment of 52.606 Km with cold Applied Tape Group-E Chaksu-Matura LOA No:24706497	116	RUNNING	
37	Providing Tank Base Protective Coating For Crude Oil Tank At Chaksu LOA No:24710453	38	RUNNING	
38	Maintenance and inspection OF Crude Oil Storage of Tank No-MT-02 at MUNDRA LOA No:24792842	611	RUNNING	
39	Removal of old coat & wrap Priming at Rohat T Point	14	RUNNING	
40	Coating Refurbishment of 4.550 Kms with PU Coating at Ramsar-Chaksu LOA No: 24826460	195	STARTED	
41	Maintenance and inspection OF 500 KL Tank at SMPL Panipat LOA No:24846005	74	STARTED	
42	Maintenance and inspection OF 250 KL Tank at NRPL Panipat LOA No:24846001	64	STARTED	
43	Maintenance and inspection OF 500 KL Tank at NRPL Ambala LOA No:24845944	74	STARTED	
44	Maintenance and inspection OF 500 KL Tank at NRPL Bijwasan LOA No:24845841	74	STARTED	

45	Isolation of interconnecting pipings between booster suction & inter tank transfer LOA No:	11	STARTED	
46	Coating Refurbishment of 69.156 Kms with PU Coating Chaksu LOA No: 24868151	206	STARTED	
47	Coating Refurbishment of 69.156 Kms with PU Coating at WRPL Sendra LOA No: 24875359	478	STARTED	